Electronics
Digital Multimeters

Terry Sturtevant

Wilfrid Laurier University

May 24, 2012

Digital Multimeter (DMM)

Digital Multimeter (DMM)

- allows measurement of multiple things

Digital Multimeter (DMM)

- allows measurement of multiple things

  voltage, current, resistance

Digital Multimeter (DMM)

- allows measurement of multiple things

  voltage, current, resistance
- allows measurement of both DC (ie. static) and AC (i.e. time-varying) quantities

Sample multimeter - Amprobe 33XR



Display section - Amprobe 33XR

Control section - Amprobe 33XR

Control section - Amprobe 33XR

DC voltage

Control section - Amprobe 33XR

AC current

Control section - Amprobe 33XR

DC current

Control section - Amprobe 33XR

Control section - Amprobe 33XR

Control section - Amprobe 33XR

DC voltage

DC current

Control section - Amprobe 33XR



Connection section - Amprobe 33XR



Connection section - Amprobe 33XR



Connection section - Amprobe 33XR



Connection section - Amprobe 33XR



Connection section - Amprobe 33XR



Voltage measurement



Voltage measurement



Voltage measurement



Voltage measurement



Voltage measurement



Voltage measurement



Current measurement



Current measurement



Current measurement



Current measurement



Current measurement



Current measurement



Resistance measurement



Resistance measurement



Resistance measurement



Resistance measurement



Resistance measurement



Resistance measurement

Recap:

Recap:

1. Voltage is always measured by a meter **in parallel** with the device being measured with the leads in the *common* and *voltage* terminals.

Recap:

1. Voltage is always measured by a meter **in parallel** with the device being measured with the leads in the *common* and *voltage* terminals.
2. Current is always measured by a meter **in series** with the device being measured with the leads in the *common* and *current* terminals.

Recap:

1. Voltage is always measured by a meter **in parallel** with the device being measured with the leads in the *common* and *voltage* terminals.
2. Current is always measured by a meter **in series** with the device being measured with the leads in the *common* and *current* terminals.
3. Resistance is always measured with the power off, or preferably by removing the resistor from the circuit with the leads in the *common* and *resistance* terminals.

Recap:

1. Voltage is always measured by a meter **in parallel** with the device being measured with the leads in the *common* and *voltage* terminals.
2. Current is always measured by a meter **in series** with the device being measured with the leads in the *common* and *current* terminals.
3. Resistance is always measured with the power off, or preferably by removing the resistor from the circuit with the leads in the *common* and *resistance* terminals.